



COT STATE OF THE PROPERTY OF T

Docket No.: GAMBRO 3.3-250 (PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of: Ekdahl et al.

Patent No.: 6,806,947 🛭

Issued: October 19, 2004

For: APPARATUS FOR MONITORING A FLUID

CONDUIT

Certificate DEC 0 2 2004

of Correction

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.323

Dear Sir:

Enclosed herewith is an original and one copy of a Certificate of Correction with respect to the above-identified U.S. Patent. You are hereby authorized to charge Deposit Account No. 12-1095 in the amount of \$100 to cover the required fee for filing a Certificate of Correction under § 1.323.

These errors were inadvertent, occurred in good faith and do not involve any changes which constitute new matter.

We look forward to early return of the copy of the Certificate of Correction duly certified.

Dated: November 22, 2004

Respectfully submitted,

11/30/2004 NNGUYEN2 00000117 121095 6806947

01 FC:1811

100.00 DA

Michael H. Teschner Registration No.: 32,862

LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP

600 South Avenue West Westfield, New Jersey 07090

(908) 654-5000

Attorney for Applicant

528585_1.DOC

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6.806.947 **B**I

DATED

October 19, 2004

INVENTOR(S) :

Olof Ekdahl and Per-Ola Wictor

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 39, "thismanner" should read - this manner -.

Column 9, line 28, "as" should read - is -.

Column 9, line 62, "are" should read - is -.

Column 10, line 8, "thismanner" should read - this manner -.

Column 12, line 35-36, "comprising" should read - comprises -.

MAILING ADDRESS OF SENDER:
Michael H. Teschner
LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP
600 South Avenue West
Westfield, New Jersey 07090

PATENT NO. 6,806,947

No. of additional copies 1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,806,947 Bi

DATED

October 19, 2004

INVENTOR(S)

Olof Ekdahl and Per-Ola Wictor

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 39, "thismanner" should read - this manner -.

Column 9, iine 28, "as" should read - is -.

Column 9, line 62, "are" should read - is -.

Column 10, line 8, "thismanner" should read - this manner -.

Column 12, line 35-36, "comprising" should read - comprises -.

MAILING ADDRESS OF SENDER: Michael H. Teschner LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP 600 South Avenue West

Westfield, New Jersey 07090

528597 1.DOC

PATENT NO. 6,806,947

No. of additional copies 1